



## Refinish

# DuPont™ Sontara® PS-3970S™ & PS-3990S™ Solvent Pre-Saturated Cleaner Wipes

### Description

---

DuPont™ Sontara® PS-3970S™ & PS-3990S™ are multi-purpose surface cleaners that leave no surface residue. The unique solvent blend in DuPont™ Sontara® PS-3970S™ is formulated for mid temperature conditions (i.e. 70°F). DuPont™ Sontara® PS-3990S™ is specially formulated for high temperature conditions (i.e. 90°F).

DuPont™ Sontara® Pre-Saturated Cleaner Wipes are conveniently packaged in individual packets. It is recommended for use as a multi-purpose cleaner for all DuPont topcoat systems. The solvent blend was formulated to remove wax, grease, silicone, dirt, tar, insect remnants, sanding dust, compound sludge prior to topcoat.

### General Information

---



#### Components

DuPont™ Sontara® PS-3970S™ Mid Temperature Pre-Saturated Cleaner Wipes  
DuPont™ Sontara® PS-3990S™ High Temperature Pre-Saturated Cleaner Wipes

---

### Mix Ratio/Viscosity

Ready to use.

### Application

---

#### Substrates

Sanded substrates  
OEM finishes  
Cured, repainted surfaces  
Sanded primers

*Note: Do not use on unprimed plastic or fiberglass substrates due to possible static buildup, which may cause a flash fire.*

---

#### Surface Preparation

Use DuPont™ Sontara® PS-3970S™ & PS-3990S™ to remove wax, grease, silicone, dirt, tar, insect remnants, sanding dust, compound sludge prior to topcoat.

---



#### Application

- Wipe the substrate with a clean DuPont™ Sontara® Solvent Pre-Saturated Cleaner Wipe to substrate to remove wax, grease, silicone, dirt, tar, insect remnants, sanding dust, and compound sludge prior to topcoat.
- Apply moderate pressure and maintain even strokes from end to end when wiping the substrate. Fold repeatedly to expose a clean wipe surface.
- Follow immediately by wiping the surface thoroughly dry with a clean DuPont™ Sontara® cloth (E-R4142 or E-R-4143).
- For hard to remove surface contamination, repeat the previous process steps.



Refinish

## DuPont™ Sontara® PS-3970S™ & PS-3990S™ Solvent Pre-Saturated Cleaner Wipes

---

### *Tips for Success*

- Do not allow solvent cleaner to dry on the surface. If this does occur, simply wipe again with another pre-saturated wipe then wipe dry.
- Do not use DuPont™ Sontara® Pre-Saturated Solvent Cleaner Wipes on unprimed plastic or fiberglass substrates, due to possible static buildup; the use of this surface cleaner on unprimed plastic or fiberglass may cause a flash fire.

### Physical Properties

---

VOC: DuPont™ Sontara® PS-3970S™ 6.2 lbs/gal ready to use in a pre-saturated wipe.  
DuPont™ Sontara® PS-3990S™ 6.4 lbs/gal ready to use in a pre-saturated wipe.  
Flash Point: See MSDS.

### VOC Regulated Areas

---

These directions refer to the use of products which may be restricted or require special mixing instructions in VOC regulated areas. Follow mixing usage and recommendations in the VOC Compliant Products Chart for your area.

### Safety and Handling

---

For industrial use only by professional, trained painters. Not for sale to or use by the general public. Before using, read and follow all label and MSDS precautions. If mixed with other components, mixture will have hazards of all components.

Ready to use paint materials containing isocyanates can cause irritation of the respiratory organs and hypersensitive reactions. Asthma sufferers, those with allergies and anyone with a history of respiratory complaints must not be asked to work with products containing isocyanates.

Do not sand, flame cut, braze or weld dry coating without a NIOSH approved air purifying respirator with particulate filters or appropriate ventilation, and gloves.

Please visit: [www.performancecoatings.DuPont™.com](http://www.performancecoatings.DuPont™.com) to view or print an addition copy of this "Technical Product Data" sheet.

*The miracles of science™*K-16298  
E-R 4536

09/07